Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Enerplus Resources (USA) Corporation
Well Name/Number: Porky-Harold 9-13-HSU
Location: SW SW Section 9 T24N R54E
County: Richland, MT; Field (or Wildcat) Wildcat
Air Quality
(possible concerns)
Long drilling time: No, 25-35 days drilling time.
Unusually deep drilling (high horsepower rig): <u>Triple derrick rig to drill a single lateral Bakken</u>
Formation horizontal well, TVD 9,692'/MD 15,925'.
Possible H2S gas production: Slight chance of H2S.
In/near Class I air quality area: No, Class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, if productive, DEQ air quality permit required
under rule 75-2-211.
Mitigation:
\underline{X} Air quality permit (AQB review)
X Gas plants/pipelines available for sweet gas
Special equipment/procedures requirements
Other:
Comments: Existing pipeline for gas in the area. No concerns.
Water Quality
(possible concerns)
Salt/oil based mud: Yes to intermediate string and horizontal lateral will be drilled with oil based invert
drilling fluids. Surface casing hole to be drilled with freshwater and freshwater mud.
High water table: No, high water table expected.
Surface drainage leads to live water: Yes, nearest drainage is an unnamed ephemeral tributary drainage to
West Charlie Creek, about 1/4 mile to the west and ½ of a mile to the east is West Charlie Creek from thi
ocation. Stock pond appears to be built in this part of West Charlie Creek about 1/4 of a mile to the
northeast of this location.
Water well contamination: No, closest stock water well is about 3/8 of a mile to the northeast of this
ocation and is only 40' in depth. Surface hole in this well will be drilled with freshwater and freshwater nud system. Steel surface casing will be run and cemented to surface from 1627' to protect groundwater
No concerns. Porous/permeable soils: No, silty sandy clay soils.
Class I stream drainage: No, Class I stream drainages.
Mitigation:
X Lined reserve pitX Adequate surface casing
Auequate surface casing Berms/dykes, re-routed drainage
Bernis/dykes, re-routed dramage Closed mud system
Closed mud system Off-site disposal of solids/liquids (in approved facility)
ATT-NIE UINDONAL DE NORUN/HUHIUN UIT ADDIOVEU TACHIEV)
Other: Comments: 1627'+/- surface casing well below freshwater zones in adjacent water wells. Also,

Soils/Vegetation/Land Use

(possible concerns)
Steam crossings: None, only ephemeral drainages.
High erosion potential: No, location has a moderate cut of 15.8' and a moderate fill of 18.3', required.
Loss of soil productivity: None, location to be restored after drilling well, if nonproductive. If productive
unused portion of drillsite will be reclaimed.
Unusually large wellsite: No, large well site 430'X300'.
Damage to improvements: Slight, surface use appears to be grazing land.
Conflict with existing land use/values: Slight
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
<u>X</u> Other: <u>Requires DEQ General Permit for Storm Water Discharge Associated with</u>
Construction Activity, under ARM 17.30.1102(28).
Comments: Access will be over existing county road, #301. About 3,785' of new access road will be built
from existing county road, #301, into location. Cuttings will be disposed of in lined reserve pit. Pit will
have the liner folded over the cuttings and the pit backfilled with subsoils. Oil based drilling fluids will be
recycled. Completion fluids will be hauled to a commercial Class II disposal. No concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: <u>Closest residence is about 3/8 of a mile to the northeast from this</u>
location.
Possibility of H2S: _Slight chance of H2S.
Size of rig/length of drilling time: Large triple drilling rig and 25 to 35 days drilling time.
Mitigation:
<u> </u>
_X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: 1627'+ is adequate surface casing cemented to surface with working BOP stack
should mitigate any problems. Distance sufficient to mitigate noise.
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: Species identified as threatened by the USFWS are Pallid Sturgeon,
Interior Lease Tern, Piping Plover and Whooping Crane. Species listed as candidate species are the
Greater Sage Grouse and Spragues Pipit. NH tracker website for this Township and Range lists no species
of concern.
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:

Comments: Private surface lands. Location is not near any river. Threatened species should not
be a concern at this wellsite. No concerns.
•
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other: Comments: _Private surface lands. No concerns.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: Development well, fouth well in this spacing unit. No concerns.
Remarks or Special Concerns for this site
Fourth Bakken horizontal well in this spacing unit.
Summary: Evaluation of Impacts and Cumulative effects
A single lateral Bakken Formation horizontal well, TVD 9,692'/MD 15,925'. No long term impacts
expected. Some short term impacts will occur.
expected. Some short term impacts will occur.
I conclude that the approval of the subject Notice of Intent to Drill (does/does not) constitute a major
action of state government significantly affecting the quality of the human environment, and (does/does
not) require the preparation of an environmental impact statement.
Prepared by (BOGC): /s/Steven Sasaki
(title:) Chief Field Inspector
Date:January 6, 2011
Other Persons Contacted:
_ Montana Bureau of Mines and Geology, Groundwater Information Center website
(Name and Arrana)
(Name and Agency)
_Richland County water wells
(subject discussed)
_January 6, 2011
(date)
(unic)

(Name and Agency)
Threatened or Endanger species
(subject discussed)
January 6, 2011
(date)
Montana Natural Heritage Program Website (FWP) (Name and Agency) Heritage State Rank= S1, S2, S3, T24N R54E
(subject discussed)
<u>January 6, 2011</u>
(date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: